





**Installation:**

1st nut should be spanned with 40 - 45Nm.  
 2nd nut should shall be brought at least to a snug-tight condition, with special care being given to avoid over-tightening.  
 Nut-marking should be made acc. to figure after torque.

**Maintenance:**

Visual inspection of bolt torque and any loose items is made 1 year after installation, and afterwards every 5th year.  
 Check if the marking from bolt torque is still straight.  
 Check if the corrosion protection system is satisfactory.  
 Any findings must be repaired as soon as possible.



ITEM NO.	PART NUMBER	DESCRIPTION	QTY.
1	CB-L60-110 300	C bracket L60-110	2
2	M12x220 DIN976	Horizontal pole bracket pin-bolts	4
3	Washer ISO 7089 - 12		8
4	ISO - 4032 - M12 - W - N		8
5	ISO - 4035 - M12 - N		8

Rev.:	Int.:	Date:	Comment		
Customer.:					
Subjekt.: Spare parts for CB and CBM L60-110					
Date.: 16-09-2021		Production no.:		Scale.: 1:3	
Order no.:		Calculation:		Int.: SP/MRF	
Drawing. No.: CB-CBM-L60-110				Note.:	
This drawing is our property and must not be copied, transferred or in any way used by a third party without our written permission					
<div style="display: flex; justify-content: space-between;"> <span>Carl C A/S Manufacturing Engineering Commerc Smedevej 2 DK-6900 Skjern Tel. +45 97351066 Fax +45 97351276 www.carl-c.com</span> <div style="text-align: right;">                     Format:A3                      Projektion:                        Tolerance: DS/EN 1090-2 DS/ISO 2768-2-L                 </div> </div>					